ORIGINAL



| 1 | Rollaid L. McDollaid |
|---|---|
| 2 | Pineview Water Company 5198 Cub Lake Road |
| | 5198 Cub Lake Road |

RECEIVED

5198 Cub Lake Road Show Low, Arizona 92801

2010 FEB 17 P 12: 11

Telephone: 928-537-4858

General Manager of Pineview Water Company, Unit MISSION DOCKET CONTROL

BEFORE THE ARIZONA CORPORATION COMMISSION

| IN THE MATER OF THE |) | DOCKET NO. W-01676A-08-0366 |
|-----------------------------|----|---------------------------------|
| APPLICATION OF PINEVIEW |) | |
| WATER COMPANY, INC. FOR AN |) | Compliance to Law Judge's Order |
| INCREASE IN ITS WATER RATES | •) | |

On February 4, 2010 Pineview Water Company ("Company") attended the Hearing in the matter of the Company's Application for an Increase in its Water Rates.

The Law Judge hearing the case ordered the Company to docket the following documents:

- ADEQ Approval of Construction of the 2 Million Gallon Tank & the 12" Main
- ADEQ Approval of Construction of the 4 Pressure Reducing Stations
- 2009 Water Use Data Sheet
- ADEQ Compliance Status Report

Per the fore mentioned order the Company, attached Exhibit A are the ADEQ Approval of Construction documents. Attached Exhibit B is the 2009 Water Use Data Sheet and attached

Exhibit C is the ADEQ Compliance Status Report.


An Original and thirteen copies of the foregoing filed this <u>12th</u> day of February, 2010 with:

Docket Control Arizona Corporation Commission 1200 West Washington Phoenix, Arizona 85007

A copy of the foregoing filed 75005.00000.053

Arizona Corporation Commission DOCKETED

FEB 17 2010



1

3

4

5

6

7

8

9

10

11

12

13

14

15

17

16

18

19

20

22

23

^ 4

this 12h day of February, 2010 to: 1 2 Ms. Lyn Farmer Chief Administrative Law Judge, Hearing Division 3 Arizona Corporation Commission 1200 W. Washington Phoenix, Arizona 85007 4 5 Mr. Steven M. Olea Director, Utilities Division 6 Arizona Corporation Commission 1200 West Washington 7 Phoenix, Arizona 85007 8 Ms. Janice Alward 9 Chief Counsel, Legal Division Arizona Corporation Commission 1200 West Washington 10 Phoenix, Arizona 85007 11 12 13 14 15 16 17 18 19 20 21 22 23



ARIZONA DEPARTMENT OF ENVIRONMENTAL QUALITY

1110 West Washington Street • Phoenix, Arizona 85007 (602) 771-2300 • azdeq.gov



APPROVAL OF CONSTRUCTION

Project Description:

Pineview Water Company. The Installation of 1-2,000,000 gallon Water Storage

Tank and Yard piping. To serve Starlight Ridge Estates.

Location:

Show Low, AZ

Project Owner:

Pineview Water Company

Address:

5198 Cub Lake Road, Show Low, AZ 85901

The Arizona Department of Environmental Quality (ADEQ) hereby issues an Approval of Construction for the above-described facility based on the following provisions of Arizona Administrative Code (A.A.C.) R18-5-507 et seq.

On August 17, 2009, ADEQ issued a Certificate of Approval to Construct for the referenced project.

On November 24, 2009 John P. Murphy, P.E., certified the following:

A final construction inspection was conducted on November 24, 2009;

The referenced project was constructed according to the as-built plans and specifications and ADEQ*s
 Certificate of Approval to Construct;

 Water system pressure and leakage tests were conducted on June 25, 2007, and the results were within the allowable leakage rates;

■ The water distribution system was disinfected according to an ADEQ-approved method; and

The applicant has the right to appeal this AOC Permit. Appeal information is on reverse side of this Permit.

Microbiological samples were collected on October 3, 2007 and November 16, 2009 and analyzed on October 4, 2007 and November 23, 2009 by Mojave Environmental Laboratory, ADHS License No. AZ0037. The sample results were negative for total coliform.

This Approval of Construction authorizes the owner to begin operating the above-described facilities as represented in the approved plan on file with the ADEQ. Be advised that A.A.C. R18-5-124 requires the owner of a public water system to maintain and operate all water production, treatment and distribution facilities in accordance with ADEQ Safe Drinking Water Rules.

FMS

PWS No.: 09-022 LTF No.: 51175

> Janak K. Desai, P.E., Manager Drinking Water Facilities Review Unit Engineering Review Section

c: TEU File No.: 20090212
CRO Approval of Construction File
Navajo County Health Department
Navajo County Planning & Zoning Department
AZ Corporation Commission

Engineer

Northern Regional Office 1801 W. Route 66 • Suite 117 • Flagstaff, AZ 86001 (928) 779-0313 Southern Regional Office 400 West Congress Street • Suite 433 • Tucson, AZ 85701 (520) 628-6733



ARIZONA DEPARTMENT OF ENVIRONMENTAL QUALITY

1110 West Washington Street • Phoenix, Arizona 85007 (602) 771-2300 • www.azdeq.gov



Benjamin H. Grumbles Director

APPROVAL OF CONSTRUCTION

Project Description:

Install 4 pressure reducing valve assemblies to service Pineview Water System,

located in Show Low/Navajo County.

Location:

Show Low, AZ

Project Owner:

Pineview Water Company

Address:

5198 Cub Lake Rd. Show Low, AZ 85901

The Arizona Department of Environmental Quality (ADEQ) hereby issues an Approval of Construction for the above-described facility based on the following provisions of Arizona Administrative Code (A.A.C.) R18-5-507 et seq.

On January 14th, 2009, ADEQ issued a Certificate of Approval to Construct for the referenced project.

On November 3rd, 2009, John P. Murphy, P.E., certified the following:

■ A final construction inspection was conducted on October 29th, 2009;

■ The referenced project was constructed according to the as-built plans and specifications and ADEQ's Certificate of Approval to Construct;

Water system pressure and leakage tests were not conducted however pressure reading were conducted at site #3 and site #4 and were within allowable range.

■ The water distribution system was disinfected according to an ADEQ-approved method; and

The applicant has the right to appeal this AOC Permit. Appeal information is on reverse side of this Permit.

Microbiological samples were collected on December 8th, 2009 and analyzed on December 9th, 2009 by Mohave Environmental Laboratory, ADHS License No. AZ0037. The sample results were negative for total coliform.

This Approval of Construction authorizes the owner to begin operating the above-described facilities as represented in the approved plan on file with the ADEQ. Be advised that A.A.C. R18-5-124 requires the owner of a public water system to maintain and operate all water production, treatment and distribution facilities in accordance with ADEQ Safe Drinking Water Rules.

DB11

PWS No.: 09-022 LTF No.: 51078

> Janak K. Desai, P.B., Manag Drinking Water Facilities

Review Unit

c: TEU File No.: 20090002

CRO Approval of Construction File Mohave County Health Department

Mohave County Planning & Zoning Department

AZ Corporation Commission

Engineer

Northern Regional Office 1801 W. Route 66 • Suite 117 • Flagstaff, AZ 86001 (928) 779–0313 Southern Regional Office 400 West Congress Street • Suite 433 • Tucson, AZ 85701 (520) 628-6733



ARIZONA DEPARTMENT OF ENVIRONMENTAL QUALTY Certificate of Approval of Construction For a Water Distribution System

| Applicant Information | | | | | | ADEQ File | Number | umber 2006 0110 LTF ID 46880 | | | | 30 | | | |
|--|----------------------------|-------------------|--------|---------|---------------------------------|--|---|------------------------------|---------------|----------|-------------|-----------------|--------------|------|---|
| Name | | Lakeside 160, LLC | | | | Project Nam | ie Sta | arlight | Ridge Est | ates U-2 | | - . | | | |
| Mail Address 1 attn: Steve Kohner | | | | | | | | | | | | | | | |
| Mail Address 2 19820 N. 7th Street #230 | | | | | | Project Location 1 mile west of Hwy 260, Wagonwheel area south of Show Low | | | | | ea south | | | | |
| City / State / Zip Phoenix Az 85024 | | | | | | | | L | | | i | | | | |
| Project Type Project Des | | | | Descri | ption | | | | | | | | | | |
| × | Press | ıre Main | | Stor | age Tank | | LF of 12" PVC water line, 5000 LF of 8" water line, 9 fire hydrants, 95 service nections & appurtenances to serve 95 residential lots | | | | | | | vice | |
| | Hydr | Tank | | Oth | er | connecti | uiis & | appurtenances | to serve | 93 168 | sidennai id | ots | | | |
| Facility | Name | Pinevi | w Wat | er Co. | | | | Facility Cap | acity | | | NA | | | |
| Street A | ddress | 5198.0 | ub Lak | e Rd. | | | ĺ | | | , | | | | | |
| Street A | ddress | 2 | | | | | | | | | | | | | |
| City / St | ate / Zi | Show I | ow Az | 8590 | 1 | | } | | | | | | | | |
| PWSID | PWSID 09022 | | | | | | Facility Capacity Affirmation By Date | | | | | e | | | |
| County | N | avajo | | | | | | NA | | | | | | | |
| Design I | Docume | nts Approv | ed | | D | ate | | Site Informa | tion | | | | | | |
| Engineers Certificate of Completion Murphy PE 2/18/08 | | | | | Location of Distribution System | | | | | | | | | | |
| As-Built | t Site Pl | an | | | Murphy | PE 2/18/08 | 3 | Township | 9N | | | Range | 22E | | - |
| As-Built Drawings and Murphy PE 2/18/08 Specifications | | | 3 | Section | 8 | | Quarter Section | | NE | • | | | | | |
| Operati | ons & N | laintenanc | e Pian | | 1 | NA | | Latitude | 34° 11′ 29″ N | | | | North | | |
| Response Letter Reed Flake 2/19/08 | | | | | 3 | Longitude | 110° 01' 59" West | | | | | West | | | |
| Other (Pressure / Leak test) Murphy PE 2/18/08 | | | | | 3 | C12: Murphy PE: 2/18/08; Bac-t: Ron McDonald/Pineview Water Co. | | | | | ater Co. | | | | |
| Variances Granted | | | | | | | | | | | | | | | |
| All documentation sealed by John P. Murphy, P.E. (except bacteriological sampling) of Tetra Tech | | | | | | | | | | | | | | | |
| g:\common\sdw\reo\Pineview\2006 0110 aoc | | | | | | | | | | | | | | | |
| Musto Blad Pal PF | | | | | - | | , | <u>َ</u> | 3/31 | 108 | 7 . | | | | |
| | Marti C. Blad, Ph.D., P.E. | | | | | Man | ager, Enginee | ring Se | rvices | · · | , | Date | | | |

Cc: Tetra Tech, 1801 W. Deuce of Clubs #230, Show Low Az 85901



ARIZONA DEPARTMENT OF ENVIRONMENTAL QUALITY

Certificate of Approval of Construction for a Water Distribution System

| Applicant Information: | | | | ADEQ Fil | le No. 990119 | | | | | | | | |
|---|-----------------------|---|---------------------------------|---------------------------------|---|-------------------------------------|------------|---------------|---------------------------------------|---------|----------|---------------------------------------|--|
| Mail Address 1 5198 Cu | | Pineview Water Co. 5198 Cub Lake Rd. | | | Project Name | , , , | | | | | | | |
| | | Show Low Az 85901 | | Project Lo | Project Location South of Show Low (Wagonw | | | | | ea) | | | |
| Project Type(s) Project | | | | Project D | Description | | | | | | | | |
| х | Pressure Main | | Storage Tank | Water line | e replacement & extension project as per the approved plans | | | | | | | | |
| | Hydro Tank | | Other | | | ı · · · | | | | · · | * | · · · · · · · · · · · · · · · · · · · | |
| Facility Name Pineview Water Co. Street Address 1 Street Address 2 City/State/Zip | | | Co. | Facility Capacity | | | | | NA | NA | | | |
| PW | SID | 09- | 022 | | | System Capacity Affirmation by Date | | | | | | | |
| County Navajo | | | | | NA | | | | | | | | |
| | Design Documents | Арр | roved | Date | Site Information | | | | | | | | |
| Engineers Certificate of Completion Murphy PE 2-10-04 | | | Murphy PE 2-10-04 | Location of Distribution System | | | | | | | | | |
| As | -Built Site Plan - | | | Murphy PE 2-10-04 3-11-04 | Township | , | 9N | Range | | | 22E | | |
| 2- | | | Murphy PE 2-10-04 3-11-04 | Section | | 4,8,9 | Qua | arter Section | | | | | |
| Ор | erations & Maintenand | e Pla | 1 | NA | Latitude | | 34 12' 35" | · | | | | North | |
| Response Letter 3-1-04 3-11-04 | | | 3-1-04 3-11-04 | Longitude | de 110 01' 15" Wes | | | | | West | | | |
| Other (Pressure/leak test) 4-13-00 etc. | | | | | | | | • | · · · · · · · · · · · · · · · · · · · | | | | |
| Variances Granted | | | | | i | | | | | | | | |
| List Variances here | | | | | | | | | <u> </u> | | | - | |
| | X | | |)ci | Field Services Manager, East | | | | | 3/17/04 | | | |
| | Harley R. Hiett, P.E. | | | | Title Date | | | | | Date | | | |

c: Murphy Engineering, 1801 W. Deuce of Clubs, Suite 230, Show Low Az 85901

ADEQ/NO, 1515 E. Cedar Ave., Suite F, Flagstaff, AZ 86004

(928) 773-2702

1(877) 602-3675 x2703

WATER USE DATA SHEET 2009

| jóka k | |
|------------------------------|------------------------|
| NAME OF COMPANY | Pineview Water Company |
| ADEQ Public Water System No. | 09-022 |

| | - | | <u>,</u> |
|---|----------------------|------------------|----------------------|
| MONTH/YEAR | NUMBER OF | Gallons Sold | Gallons Pumped |
| (Last 12 Months) | CUSTORMERS | | |
| January | 1135 | 5,381,328 | 7,055,300 |
| February | 1133 | 5,077,449 | 6,615,600 |
| March | 1136 | 4,833,810 | 5,916,400 |
| April | 1133 | 5,920,370 | 6,784,500 |
| May | 1132 | 9,483,305 | 11,367,900 |
| June | 1136 | 11,304,995 | 11,803,200 |
| July | 1139 | 12,203,750 | 12,883,800 |
| August | 1146 | 10,218,227 | 12,714,000 |
| September | 1147 | 10,964,859 | 11,163,500 |
| October | 1145 | 7,591,131 | 9,292,800 |
| November | 1145 | 6,255,083 | 9,093,800 |
| December | 1147 | 5,973,351 | 8,636,700 |
| | Totals | 95,207,658 | 113,327,500 |
| STORAGE TANK | NUMBER OF | ARIZONA DEPT. OF | WELL PRODUCTION |
| CAPACITY | EACH | WATER RESOURCES | (Gallons per Minute) |
| (Gallons) | | WELL I.D. NUMBER | |
| | | | |
| 250,000 | 1 | 55-608846 | 115.00 |
| 250,000 | 1 | 55-565467 | 130.00 |
| 70,000 | 1 | 55-521710 | 113.00 |
| 2,000,000* | 1 | 55-208625 | 147.00 |
| | | 55-208626 | 147.00 |
| | | | |
| | | <u>'</u> | |
| A. A | | | |
| | | | |
| Other Water Sources in | Gallons per Minute : | NA | GPM |
| Other Water Sources in Fire Hydrants on Systen | | NA | GPM (Yes) No |

^{*} Put into service in December 2009

Exhibit C

Arizona Department of Environmental Quality

Drinking Water Monitoring and Protection Unit
Mail Code 5415B-2
1110 West Washington Street
Phoenix, AZ 85007

Drinking Water Compliance Status Report

| System Name | System Type | Is system consecutive? | | | | | | |
|--|--|---------------------------------------|--|--|--|--|--|--|
| PINEVIEW WATER CO | Community | Yes, | | | | | | |
| System ID # | Non-transient Non-community | | | | | | | |
| 09022 | Transient Non-community | ⊠ No | | | | | | |
| | No region deficiencies | Major deficiencies | | | | | | |
| Overall compliance status Monitoring and Reporting status | | Major deficiencies Major deficiencies | | | | | | |
| Comments: None | M No major deficiencies | Major deficiencies | | | | | | |
| Comments. None | | | | | | | | |
| Operation and Maintenance status | ☐ No major deficiencies | ☐ Major deficiencies | | | | | | |
| Date of last Sanitary Survey 8-15 | -07 Inspector Steve Camp, | NRO | | | | | | |
| Major unresolved/ongoing operation a | nd maintenance deficiencies: | | | | | | | |
| unable to maintain | | uate storage | | | | | | |
| cross connection/b | ackflow problems | e water treatment rule | | | | | | |
| treatment deficienc | | | | | | | | |
| certified operator | other = | = | | | | | | |
| Comments: None | - AMERICA - AMER | | | | | | | |
| Comments. None | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| Is an ADEQ administrative order in | effect? | ☐ Yes ⊠ No | | | | | | |
| Comments: None | | | | | | | | |
| | | | | | | | | |
| | System Information | | | | | | | |
| Population Served | | 3417 | | | | | | |
| Service Connections | | 1139 | | | | | | |
| Number of Entry Points to the Distribu | tion System | 2 | | | | | | |
| Number of Sources | | 4 | | | | | | |
| Initial Monitoring Year | dia dia mandria dia mandri Mandria | 1994 | | | | | | |
| Monitoring Assistance Program (MAP) | System | ☐ Yes ☐ No | | | | | | |
| Commence Control Contr | and the second | | | | | | | |
| | Calderon, Manager | | | | | | | |
| | Water Monitoring and Protection Uni | | | | | | | |
| Phone 602-771 | | February 12, 2010 | | | | | | |
| Based upon data submitted by the water system, ADEQ has determined that this system is | | | | | | | | |
| currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and PWS is in compliance . | | | | | | | | |
| Based upon the monitoring and r | eporting deficiencies noted above, Al | DEO cannot determine if | | | | | | |
| this system is currently delivering | water that meets water quality stand | lards required by 40 CFR | | | | | | |
| this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and/or PWS is not in compliance . | | | | | | | | |
| Based upon the operation and m | aintenance deficiencies noted above, | ADEQ cannot determine if | | | | | | |
| this system is currently delivering | water that meets water quality stand | lards required by 40 CFR | | | | | | |
| 1/1/Arizona Administrative Code | Title 18, Chapter 4, and/or PWS is i | not in compliance. | | | | | | |

This compliance status report does not guarantee the water quality for this system in the future, and does not reflect the status of any other water system owned by this utility company.